161731

FPS-1 (Rev. 4/84)

INCOMING SPILL REPORT

CASE# [illegible]

RECEIVED REGION III BY: Mark Salman DATE: 9/20/84 TIME: [illegible]

REPORTED TO NRC ☐ BY: Ben Wilmoth [illegible], Wheeling, W.V.

ORGANIZATION: EPA Region III PHONE #

ADDRESS:

SPILLER: NAME: Schaeffer ~~[illegible]~~ Equipment Co. PHONE #

ADDRESS: County Route 17

Minden W.V (Fayette County)

near Oak Hill, W.V.

ORIGINAL (Red)

SPILL LOCATION: LOCATION: above

ADDRESS:

CITY: Minden COUNTY: Fayette STATE: [illegible]

NEAREST WATERWAY: Arbuckle Creek

SPILL DATA: DATE: ongoing TIME: —

MATERIAL: PCB's

SOURCE: Derelict Transformers (about 300) CAUSE:

TOTAL SPILLED: unknown IN STREAM: unknown. REMOVAL CODE:

SPILL CHANGE CONTAINMENT: NO CLEAN-UP: No.

WV DNR reported this to Ben Wilmoth 9/20/84 their # 304-489-7084

OSC Wilmoth [illegible] to perform site assessment week of Oct 1, 19[illegible]

NOTIFICATION: (NAME, DATE, & TIME) USGS: WHEELING FIELD OFFICE:

STATE/LOCAL: OTHER:

OTHER: OTHER:

AR100001

Note: TAT to conduct site assessment week of OCT. 1.

RKS: Reported to Ben by DNR, Leroy [illegible] (inspector), on 9/[illegible]/84.
DNR soil sample on site revealed 26 [illegible] ppm PCB near transformers