130555

WASTE INSPECTION REPORT

7-15-90

FROM ___ A.M. ___ P.M. TO ___ A.M. ___ P.M.

CODE

COUNTY	Montgomery 4 6
POPULATION	Hairbard Berg 8
MUNICIPALITY NO.	1 2
TYPE CASE	5

NAME OF FIRM	Milford Rivet
LOCATION—STREET OR STATE ROUTE	Jacksonville Road
RESPONSIBLE OFFICIAL	
TITLE	
PHONE NO.	
TYPE DISCHARGE OR INDUSTRY	
NO. OF EMPLOYEES OR POPULATION SERVED	
ACRES UNDER PERMIT	
ACRES ALREADY MINED	
INDUSTRIAL PRODUCTS	1. 2. 3.

TREATMENT PROCESS	NO. OF UNITS TOTAL	NO. OF UNITS IN OPERATION	REMARKS
Plant shut down for vacation			
Facilities are [illegible] wet wells			
30' x 30' [illegible]			Top of flaid 18" above natl grd
[illegible]			Top of lagoons raised
[illegible]			3 ft above ground
[illegible]			area where leak had occurred
[illegible]			
[illegible]			
[illegible]			

LOCATION OF DISCHARGE	pH	CHOR. RES.	ODOR	TEMP.	D.O.	SPEC. COND.	QTY. M.G.D.
0 MH							

RECEIVING STREAM APPEARANCE		
NAME	ABOVE DIST. APP.	BELOW DIST. APP.

WATER & WASTE QUALITY REPORT	
LOCATION	NUMBER

LAW, REGULATION OR PERMIT COND. NOS.

IND. WASTES & SEW.	
TYPE CASE NO.	
PERMIT COVERAGE	
FACILITIES COMPLIANCE	
OPERATION STATUS	
LAST VIOLATION	
VIOLATION HISTORY	
OPERATION COMPLIANCE	
MINE DRAINAGE	
OPERATOR NO.	
PERMIT NO.	
MINE OPERATION STATUS	
ALL PROGRAMS	
DATE OF REPORT	
ENFORCEMENT STATUS	
DATE OF ACTION	
CASE COMPLIANCE	

AR100062