WASTE DISCHARGE INSPECTION REPORT

Priority 3

Milford Paint	CASE	LOCATION (STREET/STATE ROUTE)	COUNTY Mont	Fairborn 164

	VALID CERTIFICATE POSTED YES ☐ NO ☐	TELEPHONE NO	INDUSTRIAL PRODUCT 1 Resins	2	FOR REPORT		
OFFICIAL Sabin Sahm	ADDRESS	TELEPHONE NO					
Walker	ADDRESS	TELEPHONE NO					

TREATMENT PROCESS	NUMBER OF UNITS TOT	IN OP	VIOLATIONS
treatment facility will be in operation. Advised Mr Sabin & Walker department by Jan 15. of completion			Impoundments continuing Violation

LAWS REGULATIONS OR PERMIT NO & COND

Chapter 101 Rules + Regulations

REMARKS

Plant is still using lagoon delay was due to problems in securing AUTOMATIC EQUIPMENT. Most of the Equipment was received by Milford Paint on or Nov 1, 1972. Spoke with Neil Lotz by phone, (Consulting Engineer) he claims Equipment will be installed and running in 6 weeks. Informed Mr Sabin to submit to us a firm cut date on which Pro-

LOCATION OF DISCHARGE	A.S.A. QUALITY REPORT NUMBER	pH	CHLOR RES	COLOR	ODOR	TEMP	D.O.	SPEC CONC	AVG DAILY FLOW MGD
No Discharge		No Samples Taken							

RECEIVING STREAM APPEARANCE

NAME	ABOVE DIS	OPP	BELOW DIS

IDENTIFICATION CO	MUN	ST	ESTAB	CASE	FAC NO 1	FAC NO 2	FAC NO 3	FAC NO 4	DATE OF INSPECTION	INSPECTING AGENCY
08	68	9	10 11	12 13	14 16	14 16	14 16	14 16	17 22	23 25
08	9125	01	01		0	0	0	1	11 05 72	WQM

FACILITY NAME	SEQ NO	DATE ORIGINAL NOTICE SENT	LATEST ACTION	DATE OF ACTION	DISCHARGE VOL	COMPLIANCE FED	INT	FAC	OP	PERMIT COMP	OPER STAT
Plating	33 34	35 40	41 42	43 48	49 52	66	67	68	69	70 3	71 72 05

PERSON GIVING SIGNATURE T. Sabin

TITLE AND DATE Director 11/3/72

SIGNATURE Inspector

EPA II

13053

AR100082